

Intermotor®

IGNITE

YOUR IMPORT SALES

Purchase Intermotor's
**IMCP16 Import Coil-on-Plug
 Promotional Assortment** featuring
 the highest quality import coils and receive
 a pair of **Boompods™ Bluetooth headphones**
FREE!





Runs to September 30, 2016
 While Supplies Last

Do the Job Right: Replace Coils in Sets

When one ignition coil fails (especially on a vehicle with higher mileage), you should replace all of the ignition coils with a new set. That's because one worn out coil means the other coils have been subjected to the same extreme heat stress and wear. In the long run, the most cost-effective repair is to replace the full set of coils.

...Especially for These Labor-Intensive Jobs

On vehicles where the rear bank coils are located under the intake plenum, ignition coil replacement can take between 2-4 hours. To save time on future jobs, replace the coils in sets using high-quality Standard® and Intermotor® Ignition Coils. Here are two SKUs that cover applications with labor-intensive jobs:

Vehicles with Rear Bank Coils Under Intake Plenum	Number of these Vehicles in Operation	Standard® and Intermotor® Ignition Coil
Lexus RX400H (08-06) Toyota Camry V6 (07-04) Toyota Highlander V6 (10-04)	982,000	 UF430
Chevrolet Equinox V6 (16-10) Chevrolet Traverse (15-10) Cadillac ATS V6 (15-13) Cadillac CTS V6 (15-08) Cadillac SRX (15-07) Cadillac STS (11-09) Cadillac XTS (15-13) GMC Terrain V6 (15-10)	1.8 Million	 UF569



Direct Fit

All Standard/Intermotor
 Ignition Coils

Intermotor®
 Genuine Import Parts

SMP
 BLUE STREAK

BESTBUY

September 2016



Deep Creep
 DC-14 (473ml)

Sea Foam



Fuel Treatment
 20003 (946ml)



Headlight Restoration Kit
 38773

SYLVANIA



Battery Hydrometer
 SP101



Anti-Freeze Tester
 SP102



E-Z-RED®



Rear Disc Brake Adjuster
 28600



Underhood Light
 111036

- 1200 Lumens 4 hours
- 700 Lumens 8 hours
- 36 LED
- Rechargeable lithium ion battery
- Bracket extends up to 78"
- Independant dual switches
- Magnets & hooks in handle
- AC and DC chargers included

CLIPLIGHT
 BETTER BY DESIGN.

Disclaimer: Products may not be available at all locations and may not be exactly as shown. Minimum purchase may be required. Flyer pricing is not guaranteed. Price and availability may vary from store to store. Please inquire at your local Bestbuy Jobber.



**QAP HEAVY DUTY
Multi Purpose Grease**
FXG000111

**QAP Multi Purpose
Grease**
FXG000211

**Quality
AUTOMOTIVE
Products™**



* EHC extra



Cobra Hydraulic 32
FBB0011740
18.9L Pail



**2nd Skin Peel-Off
Coating 312g**
17200 - Black

PlastiKote®
THE PERFECT FINISH



**Irontite
All Weather Seal**
9132-16
Ultimate Fix For
Head Gasket Leaks



233+ Performance Masking Tape

26334 - 18mmx55m (3/4")

26338 - 36mmx55m (1 1/2")

26340 - 48mmx55m (2")



Masking Tape

6545 - 18mmx55m (3/4")

6547 - 36mmx55m (1 1/2")

6548 - 48mmx55m (2")

3M

ATEQ TPMS VT55 OBDII **ATEQ's VT55 OBDII TPMS decoder / activator** **The best way to turn the tire warning light OFF!**

For the vehicles requiring an OBDII relearn, ATEQ's VT55 OBDII includes a universal OBD connector which interfaces with the vehicle's ECU via CANbus or K-line. Technicians only have to select the make of the vehicle, trigger the tire sensors and transfer the IDs.

It is that easy and fast to accurately activate and decode TPMS sensors and display the data or any faults. Training is nearly nonexistent as the whole process is displayed on-screen. Even the newest recruited technician can use the VT55 OBDII.



ATEQ



Order Part# TS55-1000



**KREW 600 Heavy-Duty
Shop Towels**
33944



Shop Towels
75120



**Kleenex Cottonelle
bath tissue, 2 ply**
17713

**SCOTT® Shop Towels
POP-UP Box**
200 Towels
75190



Brown Roll Towels
02021



**Kimberly-Clark
PROFESSIONAL®**